

A PBT transparens vivófejtéd lexán ablakának beszerelési rajza.


Assembling figure of the PBT transparent fencing mask.

Montierzeichnung der PBT Lexan Maske.

Dessin d'installation de la fenêtre Lexan du masque PBT á visière transparente.

Чертеж сборки смотрового окошка защитной фехтовальной маски ПБТ типа ЛЕКСАН.

Diseño de montaje del visor Lexan de la careta transparente PBT.



Instructions for anti steam fluid:

Drop a little anti steam fluid onto the visor (inside)
and wipe off smoothly with a soft, absorbent textile.

DO NOT USE ANY OTHER CLEANING LIQUID!



PBT HUNGARY KFT